


## IMPORTANT SAFETY NOTICE

### White-Rodgers Announces Voluntary Corrective Action on Model 1F80-04xx, 1F83-04xx, 1F85-04xx, 1F86-04xx Thermostats


June, 2014




\*\*\*\*\*AUTO\*\*MIXED AADC 630  
CUSTOMER # GEMCNT0979  
CEDAR PARK AC SERVICE  
4410 ANGELICO LN  
ROUND ROCK, TX 78681-1698

#### White-Rodgers Four Inch 1F8X-04XX thermostats

with a private label logo. In cooperation with the U.S. Consumer Product Safety Commission and Health Canada, White-Rodgers is undertaking a corrective action plan that affects the 1F8X-04XX model thermostats. White-Rodgers has determined that there is a potential fire hazard if the thermostat is used with a "C" wire connection to the HVAC 24-VAC transformer and the AA alkaline batteries in the thermostat leak. The affected models are pictured below.




1F80-04xx



1F83-04xx



1F85-04xx



1F86-04xx

White-Rodgers requests that private label contractors:

1. Check all thermostats in your inventory to determine if you have any Model 1F80-04XX, 1F83-04XX, 1F85-04XX and 1F86-04XX thermostats. Inventory with a date code after week 1 of 2014 (also marked with a green dot ● on the thermostat, on the box and on the master carton) is not affected by field action and does not need to be returned.
2. If you do have inventory without the green dot, please return the thermostats to your distributor for credit.
3. Please check your records and contact White-Rodgers at **1-888-624-1901** to provide the name and address of any contractors or customers that purchased one or more 1F8X-04XX thermostats. White-Rodgers will use that information to provide your customers corrective action information.
4. Please re-order 1F8X-04XX thermostats to replace any inventory returned pursuant to the corrective action plan.
5. For more information regarding the recall go to the recall website: [www.regcen.com/1f8recall](http://www.regcen.com/1f8recall)

We appreciate your help and cooperation.